


SH - 4017

1. main body upper cap (aluminum).
2. 300L pulley.
3. machine head.
4. transmission shaft.
5. mixing head.
6. stainless steel bowl with supporting parts.
7. base.
8. hex-screw.
9. transmission shaft handle.
10. body.
11. case iron 3/8=60T pulley.
12. cast iron 3/8=13T pulley.
13. gear box cover.
14. 1 hp motor.
15. there level 46T=37T=27T gear.
16. main shaft.
17. 34T gear.
18. 24T gear.
19. 15T gear shaft.
20. 13T gear shaft.
21. H2.25=69T case iron gear.
22. H2.25=22T gear.
23. gear shaft.
24. up and down parts handle.
25. cast iron up and down parts.
26. 1/2 curve screw.
27. 14H (1.d) spring.
28. 14P=14T gear.
29. cast iron rack.
30. 5/8 fixing speed shaft.
31. stainless steel bowl.
32. aluminum beater.
33. aluminum hook.
34. stainless steel whip.

17. 34T 齒輪
18. 24T 齒輪
19. 15T 齒輪軸
20. 13T 齒輪軸
21. H2.25=69T 大孔內齒輪
22. H2.25=22T 小孔內齒輪
23. 齒輪軸
24. 升降把手
25. 鋼製升降機
26. 1/2 吋彈簧
27. 14H 內齒輪
28. 雙速齒輪 14P=14T
29. 鋼製排齒
30. 5/8 吋力臂
31. 光面鋼製固定軸心
32. 鋁製打蛋器
33. 鋁製打蛋球
34. 不銹鋼打蛋器



1. 本機
2. 300L 齒輪
3. 機頭
4. 齒輪架
5. 齒輪
6. 齒輪
7. 齒輪
8. 齒輪
9. 齒輪
10. 齒輪
11. 齒輪
12. 齒輪
13. 齒輪
14. 齒輪
15. 齒輪
16. 齒輪

40T=37T=27T